

Introducing

RIMLINER™

The Intelligent Solution to Tire Pressure Leaks

RIMLINER™
The Intelligent Solution to Tire Pressure Leaks



Most tire failures are caused by the loss of air pressure, leading to premature tire wear, increased fuel consumption and creating a potential safety hazard! Oxidation and porosity at the rim are seen as the major culprits. The industry standard for correcting wheel oxidation is to disassemble the tire, wire brush the area, and re-apply the protective coating. A temporary fix at best...

RIMLiner™ provides the only long term solution available in today's market. We create a barrier against the rim surface, mitigating air pressure loss due to oxidation and porosity.

RIMLiner™ is designed to withstand the most challenging of climates. We have chosen the toughest, most durable of polymers as our material. Rimliner utilizes the highest grade of thermoplastic elastomer providing excellent performance in the automotive world.

RIMLiner™ utilizes the same equipment and methodology as tire assembly. Remove the tire, simply install the flexible RIMLiner™ over the rim, and reinstall the tire. Its that simple!

- RIMLiner™ Provides an Intelligent Solution.
- RIMLiner™ Provides a barrier against the rims natural oxidation and porosity.
- RIMLiner™ Installs directly over the rim, utilizing the same equipment and methodology as the tire assembly.
- RIMLiner™ Holds the air in the tire, mitigating the migration of pressure loss through the rim.
- RIMLiner™ – The Intelligent solution.



The Facts

- Underinflation is a tire's #1 enemy.
- Underinflation leads to unnecessary tire stress, uneven wear, increased fuel consumption, loss of control and collisions.
- A tire can lose up to half it's air pressure and not appear to be flat ⁽¹⁾
- 70% of vehicles surveyed had 1 or more tires improperly inflated by >10% ⁽²⁾
- 33% have 3 or 4 tires underinflated by >10% ⁽²⁾

(1) www.betresmart.ca

(2) Rubber Association of Canada 2003 Tire Survey



ABC Group Sales & Marketing

241 33 Northwestern Highway, Southfield, MI, USA 48075

Tel: 248-352-0930 EXT 312